

REPLACEMENT PARTS LIST - CONTRACT W535-AC-8131

2-28-37

RECAPITULATION

Replacement parts previously reported\$7,285.53
 Total of Replacement Parts List dated 2-28-37 1,046.92
 Total Replacement Parts listed to date 2-28-37\$8,332.45
 Spare Parts Contract W535-AC-8131
 P.O. 37-1091 Invoiced 9-16-36\$3,372.11
 Spare Parts Contract W535-AC-9573
 P.O. 37-3057 Invoiced 1-9-37\$2,457.13
 Total Replacement Parts invoiced to date 2-28-37 5,829.24
 Total Government liability to date, 2-28-37, over and above the
 amount specified in article 17, as provided for in paragraph #3d,
 Item 3 of Article 15, subject contract\$2,503.21

AIR CORPS INSPECTOR'S CERTIFICATE

I certify that the articles listed on pages one and two of this report dated 2-28-37 were inspected and accepted by me in the quantities stated, and that they conform to the contract requirements for articles and parts used in the subject engine, and that the above replacement articles and parts were necessary for the continued operation of the subject engine.

Robert T. ...

 Inspector's Signature

Procurement Inspector
 U. S. Army Air Corps

 Title and Rank

3-16-37

 Date

REPLACEMENT PARTS LIST - CONTRACT W535-AC-8131

<u>Part No.</u>	<u>Part Name and Description</u>	<u>No.of Units</u>	<u>Unit Price</u>	<u>Total</u>
503502	Crankcase R.H. and L.H.			
503503	Inspection after 5 hours endurance running disclosed cracks running from the diaphragm lightening holes to the flange at the crankcase joint between the two halves. A new crankcase is being fabricated under P.O. 37-3435. This crankcase was held up, pattern revised and new castings ordered as described in E.S.M.R. Serial No. E-57-285-57 and Serial No. E-57-285-59. Reworking pattern equipment and additional labor charges to incorporate latest changes in crankcase assembly now being machined under P.O. 37-3435	1	997.00	997.00
503832	Finger Assembly - distributor support. In order to avoid delay if needed, the above part, taken from the Replacement Parts stock as reported 12-31-36 was replaced.	1	26.68	26.68
503750	Head clockwise distributor In order to avoid delay if needed, the above part, taken from the Replacement Parts stock as reported 12-31-36 was replaced.	1	15.87	15.87
503748	Finger assembly clockwise distributor In order to avoid delay if needed, the above part, taken from the Replacement Parts stock as reported 12-31-36 was replaced.	1	4.54	4.54
503771	Plate - distributor insulating In order to avoid delay if needed, the above part, taken from the Replacement Parts stock as reported 12-31-36 was replaced.	1	2.83	<u>2.83</u>
Total of Replacement Parts List dated 2-28-37				\$1046.02