

REPLACEMENT PARTS LIST

CONTRACT W535AC-12741

TWIN CYLINDER ENGINE

<u>PART NO.</u>	<u>NAME AND DESCRIPTION</u>	<u>NO. OF</u> <u>UNITS</u>	<u>UNIT</u> <u>PRICE</u>	<u>TOTAL</u>
503607	Connecting rod - blade The failure of the forked connect- ing rod damaged the bearing and scratched the bore of the blade connecting rod, necessitating regrinding. Rework present part	1	7.20	7.20
503610 503611	Bearing - Connecting Rod The connecting rod bearing was damaged by the failure of the connecting rod, necessitating re- placement with one oversize on the O.D. and undersize on the I.D. New part, no change in design	1	76.10	76.10
TOTAL REPLACEMENT PARTS LIST DATED 3-15-40.....				\$83.30

REPLACEMENT PARTS LIST

RECAPITULATION

CONTRACT W535AC-8131

Credit allowed on reduction gears (Progress Report 2-28-39 ...\$ 492.66

CONTRACT W535AC-12741

Multi-Cylinder Engine

Total of Replacement Parts Previously Reported..\$7357.35

Twin Cylinder Engine

Total of Replacement Parts Previously Reported \$1275.88

Replacement Parts List 3-15-40.....\$ 83.30

Total Government Liability on Spare Parts used in the engine to date, 3-15-40, over and above the amount specified in Article 18 as provided for in paragraph 2b1, and 2b2 Item 10 of Article 16 subject Contract.....\$8716.53

CONTINENTAL MOTORS CORPORATION

J. W. Kinnucan

March 15, 1940

AIR CORPS INSPECTOR'S CERTIFICATE

I certify that the articles listed on page one of this report dated 3-15-40 were inspected and accepted by an Air Corps Inspector in the quantities stated, and that they conform to the contract requirements for articles and parts used in the subject engine, and that the above articles were necessary for the continued operation of the subject engine.

Joseph Haddad
Inspector's Signature
Joseph Haddad
Junior Mechanical Engineer
U.S. Army Air Corps